

Fw: Gasco Report of Upper Alluvium Extraction Well Installation , Development, and Step Testing

Sean Sheldrake to: bayuk.dana

08/11/2012 08:55 AM

Cc: "Mullin, Jeanette", "Peterson, Lance", coffeyse

Dana, Please see the attached comments on the subject report. Let us know if you have any questions.

Thank you.

S

1 attachment



Comments_Gasco UA Extraction Wells_Development Step Testing Report.docx

Sean Sheldrake, RPM, Unit Diving Officer USEPA, Region 10
Environmental Cleanup Office 1200 Sixth Avenue, Suite 900, ECL-110 Seattle WA 98101-3140 sheldrake.sean@epa.gov Phone: 206.553.1220

Region 10 Dive Unit: http://www.epa.gov/region10/dive

Like us on Facebook! http://www.facebook.com/EPADivers

EPA Divers only: http://204.47.216.153:9876/r10/infopage/cleanup.nsf/webpage/DSBtechdirector

Portland Harbor Cleanup: http://www.epa.gov/region10/portlandharbor

Green Cleanups: http://yosemite.epa.gov/R10/extaff.nsf/programs/greencleanups

Green Cleanups (EPA only):

http://204.47.216.153:9876/r10/infopage/cleanup.nsf/webpage/greener+cleanups

Health and Safety (EPA only): http://204.47.216.153:9876/r10/infopage/cleanup.nsf/webpage/H&SecI

Deliveries: Parking Garage mailroom (1st floor)

Visitors: Check-in @ PERC / Service Center on 12th floor:

http://yosemite.epa.gov/r10/extaff.nsf/Homepage/Visiting+Seattle ----- Forwarded by Sean Sheldrake/R10/USEPA/US on 08/02/2012 05:56 AM -----

From: John Edwards < jedwards@anchorqea.com>

To: Dana Bayuk <BAYUK.Dana@deq.state.or.us>, Sean Sheldrake/R10/USEPA/US@EPA, "Lance

Peterson (PetersonLE@cdm.com)" <PetersonLE@cdm.com>, "Coffey, Scott"

<CoffeySE@cdmsmith.com>, James Peale <ippeale@maulfoster.com>, Henning Larsen

<LARSEN.Henning@deq.state.or.us>

Cc: Michael Riley mriley@anchorqea.com, Bob Wyatt mriley@anchorqea.com, Bob Wyatt mriley@anchorqea.com, Bob Wyatt mriley@anchorqea.com, Bob Wyatt mriley@nwnatural.com, "Patty Dost"

<pdost@pearllegalgroup.com>, Carl Stivers <cstivers@anchorqea.com>, "John Edwards"
<jedwards@anchorqea.com>, John Renda <jrenda@anchorqea.com>, "Matt Wilson"
<mwilson@anchorqea.com>, Carl Stivers <cstivers@anchorqea.com>, "Ryan Barth"

<rbarth@anchorqea.com>, Tim Stone <tstone@anchorqea.com>, "mdcrystal@sevenson.com"

<mdcrystal@sevenson.com>, Rob Ede <robe@hahnenv.com>, Rana Wilson <rwilson@anchorqea.com>, Ben Hung <bhung@anchorqea.com>, Kim Slinski <kslinski@anchorqea.com>, Ben Johnson
 bjohnson@anchorqea.com>

08/01/2012 11:20 AM

Date:

Subject: FW: Gasco Report of Upper Alluvium Extraction Well Installation, Development, and Step Testing

Hello Dana. Attached is the report describing the Gasco site upper alluvium extraction well installation, development and step test work. We will be sending CDs that contain the entire report, including appendices. The PDF on the CD will be linked and tagged per EPA electronic delivery protocol.

John

John E. Edwards, RG, CEG

ANCHOR QEA, LLC

*Please note new extension and direct line number

6650 SW Redwood Lane

Suite 333

Portland, Oregon 97224

Main 503-670-1108, Ext 170

Direct 503-924-6170 Fax 503-670-1128 Cell 503-816-6595

ANCHOR QEA, LLC

www.anchorgea.com

Please consider the environment before printing this email.

This electronic message transmission contains information that may be confidential and/or privileged work product prepared in anticipation of litigation. The information is intended for the use of the individual or entity named above. If you are not the intended recipient, please be aware that any disclosure, copying distribution or use of the contents of this information is prohibited. If you have received this electronic transmission in error, please notify us by telephone at 5036701108Ext11.



Gasco Extraction Well Memo text tables Figures .pdf